# AA-7568 Administrative Special Permit

Demolish the detached garage.

Ms. Suzanne G. Hodges Trustee of the Hodges Family Trust 6300 Brookville Rd

# CHEVY CHASE VILLAGE NOTICE OF ADMINISTRATIVE SPECIAL PERMIT REQUEST

Please take notice that the Chevy Chase Village Building Officer and Village Manager will conduct an administrative review of a Special Permit application for the following:

APPEAL NUMBER AA-7568
MS. SUZANNE G. HODGES
TRUSTEE OF THE HODGES FAMILY TRUST
6300 BROOKVILLE ROAD
CHEVY CHASE, MARYLAND 20815

The applicants seek an administrative Special Permit pursuant to Section 8-11 of the Chevy Chase Village Building Code to demolish the detached garage.

# The Chevy Chase Village Code Sec. 8-18 states:

Any person intending to demolish, raze or tear down more than fifty (50) percent of the exterior features of an existing building, garage or accessory building within the Village must first obtain an administrative Special Permit pursuant to Sec. 8-11 for such demolition in order to ensure that such work will be carried out in such a manner that abutting property owners will not be adversely affected and that the interests of the Village in public health, safety and welfare are not jeopardized by such work.

Additional information regarding this case may be obtained at the Chevy Chase Village Office between the hours of 9:00 a.m. and 5:00 p.m. Monday through Friday, may be viewed on the Village website at www.chevychasevillagemd.gov or you may contact the office for this information to be mailed to you.

This notice was mailed (and emailed where possible) to abutting property owners on the 23<sup>rd</sup> day of August, 2019. Abutting or confronting property owners or any aggrieved resident may, within fifteen (15) days of the date the notices are issued, submit written comments and request that the application be submitted to the Board of Managers in accordance with Section 8-10 of the Chevy Chase Village Building Code.

Chevy Chase Village Office 5906 Connecticut Avenue Chevy Chase, Maryland 20815 301-654-7300



August 23, 2019

Mr. Wiley Hodges & Ms. Suzanne Hodges 6300 Brookville Road Chevy Chase, MD 20815

Dear Mr. Hodges & Mrs. Hodges:

Please note that your request for an administrative Special Permit to demolish the detached garage on your property is being reviewed by the Building Officer and Village Manager.

A public notice was mailed to abutting and confronting property owners on the 23<sup>rd</sup> day of August, 2019 and a sign was posted at the property. Abutting or confronting property owners or any aggrieved resident, within fifteen (15) days of the date the notices are issued, may submit written comments and request that the application be submitted to the Board of Managers in accordance with Section 8-10 of the Chevy Chase Village Building Code.

For your convenience, enclosed please find copies of the Public Notice and mailing list. Please contact the Village office if you have any questions.

Sincerely

Jessica Gebhart

Permitting and Code Enforcement

Chevy Chase Village

enclosures


# **MAILING LIST FOR APPEALS AA-7568**

MR. WILEY HODGES & MS. SUZANNE HODGES 6300 BROOKVILLE ROAD CHEVY CHASE, MD 20815

Adjoining and confronting property owners	
Mr. & Mrs. J.W. Rayder	Mr. & Mrs. Matthew Leggett
Or Current Resident	Or Current Resident
14 Oxford Street	16 Oxford Street
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Mr. & Mrs. Roger Feldman	Mr. & Mrs. Marc E. Gordon
Or Current Resident	Or Current Occupant
18 Oxford Street	20 Oxford Street
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Mr. & Mrs. Ashton Wiltshire	Dr. & Mrs. Jon C. White
Or Current Resident	Or Current Resident
26 Oxford Street	15 Newlands Street
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Ms. Susan Morgenstein	Mr. & Mrs. Jim Todaro
Or Current Resident	Or Current Resident
16 Newlands Street	104 Newlands Street
Chevy Chase, MD 20815	Chevy Chase, MD 20815
Mr. & Mrs. Christopher Brown	Mr. & Mrs. Thomas B. Leachman
Or Current Resident	Or Current Resident
106 Newlands Street	103 Newlands Street
Chevy Chase, MD/20815	Chevy Chase, MD 20815

I hereby certify that a public notice was mailed, and emailed where possible, to the aforementioned property owners on the 23rd day of August 2019.

Jessica Gebhart
Permitting and Code Enforcement Coordinator
Chevy Chase Village
5906 Connecticut Avenue
Chevy Chase, MD 20815



# **Chevy Chase Village**

# Application for an Administrative Special Permit

Chevy Chase Village Code Section 8-1 defines a Special Permit as permission granted by the Board of Managers in accordance with Article II Division B of this Chapter [8], to construct, install, remove or alter a structure or planting, or take other action where such permission is required by this Chapter. The administrative Special Permit is a written authorization from the Building Officer and Village Manager pursuant to Sec. 8-11 permitting construction in a manner not otherwise allowed by the Village Code.

Subject Property: 6300 Brookville Road									
Describe the Proposed Project: Demo existing garage and rebuild two car garage									
Applicant Name(s) (List all property owners): Susie & Wiley Hodges									
Daytime telephone: 650-200-5290 Cell: 650-200-5290									
E-mail: Susie@hodgesfamily.com									
Address (if different from property address): 2833 Juniper St, San Mateo CA. 94403									
For Village staff use: Date this form received: August 8, 2019 Special Permit No: AA-7568									

Filing Requirements:

Applications will be reviewed for satisfaction of all requirements and are not considered complete until approved as such by staff.

Completed Chevy Chase Village Application for an Administrative Special Permit (this form)

Completed Chevy Chase Village Building Permit Application

Completed Website Posting Notice

V

A boundary survey or plat diagram with a margin of error of one tenth of a foot or less showing all existing structures, projections and impervious surfaces.

Surveys, plats, engineering reports, construction plans/specifications or other accurate drawings showing boundaries, dimensions, and area of the property, as well as the location and dimensions of all structures/fences/walls/etc., existing and proposed to be erected, and the distances of such structures/fences/walls/etc., from the nearest property lines. These drawings shall incorporate and display reference dimensions from the boundary survey or plat diagram required above.

Copy of Covenants, except for Special Permits authorized by Secs. 8-21, 8-26 or Chapter 25 of the Chevy Chase Village Code.

Applicable Special Permit fee listed in Chapter 6 of the Village Code.

### **Affidavit**

I hereby certify that I have the authority to submit the foregoing application, that all owners of the property have signed below, that I have read and understand all requirements in this matter. I hereby authorize the Village Manager, or the Manager's designee, to enter onto the subject property for the purposes of assessing the site in relation to this special permit request. I hereby declare and affirm, under penalty of perjury, that all matters and facts set forth in the foregoing application are true and correct to the best of my knowledge, information and belief.

Applicant's Signature:		Date:	29 July 2019
Applicant's Signature:	Syane g Hodge	Date:	29 July 2019

**Describe the basis for the Special Permit** (Applicants should become familiar with the pertinent sections of the Village Code. Attach additional pages as needed):

Describe the reasons why approval of the Special Permit would not adversely affect the public health, safety or welfare or the reasonable use of adjoining properties:

Accessory structure with slate roofing, 2x4 framing, 2x6 roofing trusses and cedar siding, and
concrete slab to be removed and evacuated in dumpsters. During demolition, structure and
concrete slab will be handled in such a way as to generate low levels of construction dust. In
particular the painted material such as the cedar siding will be removed in such a way as to not disturb the paint and, therefore, generate airborne concentrations of lead). We will follow OSHA's
rules and regulations in Title 29 of CFR 1962.62 concerning the handling of led based paint.  Describe the reasons why the Special Permit can be granted without substantial impairment of the intent and purpose of Chapter 8 or Chapter 25 of the Chevy Chase Village Code:
Per section 8-11 article 4 an Administrative Special Permit is granted for demolition of building and in
this case an accessory building—a garage.
Per Section 8-7, we will also place dumpster on the driveway near the existing garage during the
demolition phase—for one week. A permit for the dumpster will be needed. If necessary, we will need a permit for a portable toilet as well, again place well inside the property.

In exercising its powers in connection with an administrative special permit request, the Chevy Chase Village Building Officer and the Village Manager may reverse or affirm, wholly or partly, or may modify the requirement, decision or determination as it deems appropriate.

Special Permit Filing Fees	Checks Payable To:	Chevy Chase Village 5906 Connecticut Ave. Chevy Chase, MD 20815
Per Village Code Sec 6-2(a)(24):   \$300.00 for new construction.  \$150.00 for replacing existing non-conformities.  \$2,250.00 for demolition of main building.  \$300.00 for demolition of accessory building or structure.  \$300.00 for fences, walls, play equipment, trees, hedges, shrubbery in the public right-of-way.  Fee Paid:	Date Paid: Staff Signature:	8.25
	Approved to Issue Building Posigned by the Building Office  Date:  Signature: Building Officer  Signature: Village Manager	

CONSUMER INFORMATION NOTES:

1. This plan is a benefit to a consumer insofar as it is required by a lender or a title insurance company or its agent in connection with contemplated transfer, financing or re-financing.

2. This plan is not to be relied upon for the establishment or location of fences, garages, buildings, or other existing or future improvements.


- 3. This plan does not provide for the accurate identification of property boundary lines, but such identification may not be required for the transfer of title or securing financing or re-financing.
- 4. Building line and/or Flood Zone information is taken from available sources and is subject to interpretation of originator.

5. No Title Report furnished.

### Notes:

- 1. Setback distances as shown to the principal structure from property lines are approximate. The level of accuracy for this drawing should be taken to be no greater than plus or minus 2 feet
- 2. Fences, if shown, have been located by approximate methods.
- 3. No property corners Confirmed.

4. REVISED: 5.7-19



# BROOKVILLE ROAD

(30' R/W)

(BROOKVILLE-TENNALLYTOWN ROAD-PER PI

LOCATION DRAWING **LOT 11, BLOCK 54** SECTION No 2 CHEVY CHASE

MONTGOMERY COUNTY, MARYLAND

SURVEYOR'S CERTIFICATE THE INFORMATION SHOWN HEREON HAS BEEN BASED UPON THE RESULTS OF A FIELD INSPECTION PURSUANT TO THE DEED OR PLAT OF RECORD. EXISTING PURSUANT TO THE MEAN OF BEEN FIELD LOCATED BASED UPON MEASUREMENTS FROM PROFERTY MARKERS FOUND EVIDENCE OF LINES OF APPARENT OCCUPATION.

MARYLAND PROPERTY MINE SURVEYOR REG. NO. 587 Expires: 04-02-2021

REFERENCES PLAT BK. PLAT NO. 106



SNIDER "ASSOCIATES LAND SURVEYORS 19544 Amaranth Drive Germantown, Maryland 20874 1/948-5100 Fax 301/948-1286 301/948-5100

		ww.snidersurvi	
Liber	DATE OF LOCATIONS	SCALE:	1" = 30'
	WALL CHECK:	DRAWN BY:	K.D.S.
FOLIO	HSE. LOC.: 04-10-19	JOB NO.:	19-01268

6300 Brookville Road Photos of Existing Garage





# **ASCEND CONSTRUCTION COMPANY**

1069 WEST BROAD ST, SUITE 915 FALLS CHURCH, VA 22046 NAJAFI@ASCEND-GC.COM 202-684-1074

AUGUST 16, 2019

CHEVY CHASE VILLAGE 5906 CONNECTICUT AVE CHEVY CHASE, MD 20815

RE: Means & Methods-Demolition of Exisiting Detached Garage at 6300 Brookville Road, Chevy Chase, MD 20815

# To Whom It May Concern:

This letter is to attest and confirm that the demolition and removal of construction materials and debris will at all times be done in accordance with all applicable Chevy Chase Village and Montgomery County codes and ordinances, as well as in accordance with the requirements of any and all permits, including demolition permits and Historic Area Work Permits issued in conjunction with said work.

- Prior to start of Demolition, Ascend Construction Company, will prepare the site and install all sediment controls and tree protection.
- Prior to commencing demolition activities, the detached garage will be hosed down
  with water in order to minimize any dust resulting from the demolition.
- Work crews will make every effort to park in the driveway and on the side street at Newlands St near the southern side of the property.
- The demolition will require 2-3 days.
- The demolition will be done by hand. No machinery will be used. The debris will be loaded into a 30-yard dumpster. This phase will take 2-3 days. We will start the process from the top down. We will have the dumpster parked in the client's driveway and dispose of the debris off site.

The demolition of the existing detached garage at 6300 Brookville Road, Chevy Chase MD 20815 should not affect the health, safety or welfare or the reasonable use of adjoining properties. The granting of the Special Permit will not impair the intent or purpose of Chapter 8 of the Chevy Chase Village Code.

Kind regards,

Majid Najafi President

Ascend Construction Company

202-684-1074

www.ascenddesignbuild.com

# H & D Environmental LLC.

3826 Irongate Lane Bowie, Maryland 20715 E-mail: <u>Jewelhbowie1@email.com</u> Voice: 301-266-8629

August 16, 2019

Chevy Chase Village 5906 Connecticut Avenue Chevy Chase, MD 20815

RE: Limited Pre-Alteration Survey for Lead-Based Paint Chip & Asbestos Containing Building Materials 6300 Brookville Road, Chevy Chase Md 20815

Chevy Chase Village:

H&D Environmental LLC (H&D) has conducted a limited pre-alteration paint chip survey for Lead-Based Paint (LBP) and Asbestos Containing Building Materials (ACBM), within a home's garage located at 6300 Brookville Road, Chevy Chase Maryland 20815

The survey was conducted in areas of the home on structures that will be disturbed as a result of planned demolition activities. This report summarizes findings from the sampling performed by H&D Environmental LLC on August 8, 2019. H&D Environmental LLC's Industrial Hygienist Ms. Jewel A. Howard (Certification #19013481) conducted the survey at the dwelling.

The survey entailed performing a walk through of the garage, to verify the presence of asbestos and lead based paint within the demolition areas and sampling any suspect material previously not identified.

# ASBESTOS BULK SAMPLING

During the asbestos sampling, H&D Fnvironmental LLC collected Four (4) bulk samples of suspect asbestos containing building materials (ACBM) from a specified location identified for planned demolition.

- Interior Drywall
- Interior Joint Compound
- Exterior Window Glaze
- Exterior Door Caulking

The samples were submitted to the laboratory for analysis via Polarized Light Microscopy (PLM) and using NIOSH method 7420. AMA Analytical Services, Inc. located at 4475 Forbes Blvd, Lanham, Md 20706. AMA is a AIHA accredited laboratory. National Voluntary Laboratory Accreditation Program (NVLAP)-accredited laboratory, and recognized by EPA for bulk samples, lead paint, soil and lead & asbestos air sample analysis.

According to EPA regulations, any material containing 1% asbestos is considered an Asbestos Containing Building Materials (ACBM). The analytical results indicate that None of the samples collected contained asbestos at levels greater than 1%. The results are summarized in Table 1 and the laboratory analytical data sheets are included in Appendix B.

TABLE 1: BULK SAMPLING RESULTS; 6300 Brookville Road, Chevy Chase Md 20815 August 8, 2019									
Sample #	Location	Appearance	Result						
8082019-6300- 01	Drywall	Multi-Layered	None Detected						
8082019-6300- 02	Joint Compound	White Homogenous	None Detected						
8082019 <b>-</b> 6300- 03	Exterior Window Glaze	Off-White Homogenous	None Detected						
8082019-6300- 04	Exterior Door Caulking	White Homogenous	None Detected						

# Sampling and Analysis Method for Lead

Paint chips samples were collected by scraping paint from the surface into a re-closable plastic bag. All layers of paint were collected. The collected samples were placed in clean plastic sample tubes and delivered to AMA Analytical Services, Inc. located at 4475 Forbes Blvd, Lanham, Md 20706 for analysis. Clean gloves were used prior to collection of each sample. The sample bags were labeled with a unique number for every sample and listed in the chain of custody form.

The samples were analyzed by AMA using NIOSH method 7420. AMA is an AIHA accredited laboratory, recognized by EPA for lead paint, soil, dust and air sample analysis.

### Results

Specific sample locations and analytical results for paint chips samples collected from the building are listed in Tables 2.

	TABLE 2: Lead Paint Chips Samp	oling Results		
	6300 Brookville Road, Chevy Chas August 8, 2019	e Md 20815		
Sample#	Location	Lead Concentration % by Wt	Date Sample	
8082019-6300- PC-01	Exterior Windowsill	0.53% Pb	08/08/2019	
8082019-6300- PC-02	Exterior of Building	4% Pb	08/08/2019	

# **CONCLUSIONS**

Based on the Lead-based Paint Chip sampling, the laboratory analyses indicated that the following paint chips contained lead concentrations greater than 0.5% by weight;

- Exterior Windowsill
- Exterior of the Building

# RECOMMENDATIONS

Any alterations or renovations that may disturb lead-based paint containing building structures should be conducted in accordance with all regulations governing handling lead based paint containing building structures in construction. The LBP surfaces could become LBP hazard if:

- LBP on friction surfaces is subject to abrasion.
- The LBP is damaged or deteriorated.

Building renovation and/or demolition activities have the potential to produce hazardous wastes if lead-based paint is dry scraped, dry sanded, or heated. The hazardous waste criteria for lead wastes is established under the Federal Resource Conservation and Recovery Act (RCRA), Subtitle C, as 5.0 mg/L measured with the Toxicity Characteristic Leaching Procedure (TCLP) as listed in CFR 40 Part 261. A representative sample of demolition debris should also be collected for purposes of TCLP testing to determine disposal options. The lead-based paint debris generated during demolition should be handled in accordance with all applicable federal, state and local regulations.

H&D Environmental LLC is pleased to have performed this Lead-based Screening and Asbestos Building Material survey project and written report. If you have any questions, please call us at (301) 266-8629.

Sincerely,

H&D ENVIRONMENTAL LLC.

Jewel A. Howard President /CEO



# AMA Analytical Services, Inc. Focused On Results.

Chain of Custody: 616813

Client:

Rodney Distance

Address:

9826 Marrittsville Road

Randallstown, MD 21133

Attention:

Rodney Distance

# **CERTIFICATE OF ANALYSIS**

Job Name:

Sussex Wiley Hodges

Job Location: 6300 Brookville Road, Chevy Chase,

MD 20815

Job Number: Not Provided

P.O. Number: Not Provided

Date Submitted: Date Analyzed:

08/09/2019

Report Date:

08/09/2019 08/12/2019

Date Sampled:

08/08/2019

Person Submitting:

Rodney Distance

### Summary of Atomic Absorption Analysis for Lead

AMA Sample Number	Client Sample Number	Analysis Type	Sample Type	Reporting Limit	Final Result	Comments
616813-1	8082019-6300-PC01	Flame AA	Paint Chip	0.0078 %Pb	0.53 %Pb	
616813-2	8082019-6300-PC02	Flame AA	Paint Chip	0.0082 %Pb	4 %Pb	

Analysis Method for Flame: Air, Wipes, Paints, and Soil/Solids: EPA 600/R-93/200(M)-7000B; Water: SM-3111B Analysis Method For Furnace: Air, Wipes, Paints, and Soli/Solids: EPA 600/R-93/200(M)-7010; Water: SN-3113B IV/A - Not Applicable mg/Kg = parts per million (ppm) on a dry weight basis mg/L = parts per million (ppm) %Pb = percent lead on a dry weight basis ug = micrograms ug/L = parts per billion (ppb) Note: All samples were received in good condition unless otherwise noted.

Note: All results have two significant digits. Any additional digits shown should not be considered when interpreting the

Analyst(s): Nida McGarvey

See QC Summary for analytical results of quality control samples associated with these samples.


Air and Wipe results are not corrected for any blank results. Final results for air and wipe samples are based on client supplied information not verified by this laboratory.

All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Technical Director G. Edward Carney

ME Link Cy

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NY ELAP, AlHA-LAP, or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.



# QC Summary for SDG #61396

Overview				Samples Included					
Analysis Type: Flame AA Sample Type: Paint Chip Analysis Date: 08/09/2019			616813-1 616813-2						
Preparation Blank	Report Limit	Vertification Sample	Duplicates	~	Matrix Spi	ke Analysis			
Result: 0.074 ppm	Percent Rec	overy: 98.0%	RPD: 2.6%	Spiked Sample Percent Recovery: 100.5% Spike Duplicate Percent Recovery: 96.8% RPD: 3.8%					
Matrix Blank	~	Laboratory Control Sample #1	*	Łaboratory Control Sample	#2 🗸	Reference Sample			
Result: 0.047 ppm		Percent Recovery: 114.3%		Percent Recovery: 101,959	<b>%</b>	Percent Recovery: N/A			
Calibration Curve	*	Serial Dilution / Bench Spike		Notes					
Correlation: 0.998753		Serial Dilution RPD: N/A Bench Spike Percent Recovery	r: N/A						

### Randutical Services, Inc. Focused on Results www.amalab.com AHA-LAP (#100470) NVLAP (#101143-0 4475 Porbes Blvd. • Lenham, MD 20706 (301) 459-2640 • (800) 346-0961 • Fax (301)	) NY ELAP (10920) C	MIAH	OF	CUS	TO	DY				er To Ti er Inquire	25)	305983 -F 010813 -P	
Mailing/Billing Internation:  1. Client Name Kachney Disturble  2. Address 1: 9826 Marriottavil  3. Address 2: Roadcalla four MD  4. Address 3:	Submittal  1. Job Na  2. Job Lo  3. Job #:  4. Contact	6 .		Brown D	ey t	fodge He R	5			2hase HD 208			
5. Phone # 410-814-9273 Reporting Info (Results provided as so AFTER HOURS (must be pre-scheduled) L4 Hours Limondians Late Night Limondians Disse Due L34 Hours Time Due	On as technically feasible		5. Collect Reporting BUSINESS 1	ed by:^ Info is pre IOURS	vided,	AMA wi	l assign	defaults	of 5-Da	Cell:. ay and e	mail/f	ax to contacts on file.	
Competits  Ashestos Anallysis  *PCM Air - Plense Indicate Filter Type:  O NOSH 7400 (QTY)  O Fiberglasa (QTY)  TIM Air - Pense Indicate Filter Type:  O AHERA (QTY)  O NIOSH 7402 (QTY)  O Other (specify ) (QT  PI M Bulk	TEM Bulk  LELAP  NY Sta  Residue  Vermic  TEM Dust*  L Qual. (1)  L Qual. (1)	98.4/Charfield te FLM/IEM_ il Ash	(QTY	(QTY) _(QTY) ]	QTY) _(QTY)	M	etals Ar M Ph U *Pl U *Pl U Pb U Pb U Dri	ualysis Paint Chip, Dust Wipe Air Soil/Solid_ TCLP inking Water_	(wipe t	(QTY) _(QTY) _(QTY) _(QTY)	TY) TY) STEECE		rv.
## IEPA 600 - Visual Estimate ## (QTY   EPA Point Count. (QTY   OTY   OTY   OTY   OTY   OTY   OTY   OTY   OTHER   OTT   OTHER   OTT   OTHER   OTT   OTHER   OTT   OTHER   OTT   OTHER   OTHER   OTT   OTHER   OTHER	CI Qual. fg THAP  Y) FPA 16  Y) All sam  All sam  Held data  DATE  DATE	pres/abs). 198.2/EPA 100. 10.1. pples received in ter sample. sheets are submit	m good condi	tion unless	Lae batton	noted.	ongal An Col Col U 'S <sub>1</sub> U 'S <sub>1</sub> U 'S <sub>1</sub> U Osh	nalysis lection App lection Mec pore-Trap urface Swah urface Tape. er (Sp.vály	aatus li laa (Q (	or Spore I	Trops A	comments/	
CLIENTID# SAMPLELOCATION/	ID TIME	Wipe Are	· / # /	8/3	4	8/3	P. P.	8/10	\$ \$ £	2	£ /	SPECIAL INSTRUCTION	
BOB 2012 6300 - St. Insuts A ways Do BZ Enterior Whodow 5 B4 Door Carl	1 Con 4: 00 pm			اسر اس اس			600 100 100						
PCOZ Glerior Windows PCOZ ob Bushi	5.11	poplety 6, and require blocked pate.  All 1972 to half or - 5 in delibrate of			V		ار اس						
				and of the second of the secon									
Refinquished by: Received by:	tance Vist	Signal			819			1125		- 0	UPS PolEx	Shipping Takarataban  Shipping Takarataban  (Shipping Children  (Dop Dax  (TConter	

# BWI LEAD SAFETY FOR RRP INSTITUTE


1993 Moreland Parkway, Suite 203 Annapolis, MD 21403 443-949-3952

# Certificate of Attendance and Successful Completion

Renovator Initial - English

Per 40 CFR Part 745.225

Mohammed Wajid Najafi 7109 Laverock La Bethesda, MD 20817 R-I-87816-19-0116







# AMA Analytical Services, Inc. Focused On Results.

Chain of Custody: 305983

Client: Rodney Distance

9826 Marrittsville Road Address:

Randallstown, MD 21133

Rodney Distance Attention:

# **CERTIFICATE OF ANALYSIS**

Job Name: Suspect Wiley Hodges

Job Location: 6300 Brookville Road, Chevy Chase,

MD 20815

Job Number: Not Provided

P.O. Number: Not Provided

Date Submitted: Date Analyzed:

08/09/2019 08/12/2019

Report Date:

08/12/2019

Date Sampled:

08/08/2019

Rodney Distance Person Submitting:

# **Summary of Polarized Light Microscopy**

AMA Sample Number	Client Sample Number	Total Asbestos	Chrysotile Percent	Amosite Percent	Crocidolite Percent	Other Asbestos Percent	Mineral Wool Percent	Fiberglass Percent	Organic Percent	Synthetic Percent	Other Percent		Sample Type	Sample Color	Homogeneity	Analyst ID	Comments
305983-1	8082019-6300-B1	NAD		-				-	10	-	-	90	DW	Multi	Layered	PÇ	
305983-2	8082019-6300-B2	NAD			-				-		and the	100	JC	White	Homogeneous	PC	
305983-3	8082019-6300-B3	NAD	-	=	10			3		-	tree.	100	WG	Off- White	Homogeneous	PC	
305983-4	8082019-6300-B4	NAD		**				was	**		**	100	CK	White	Homogeneous	PC	



Chain of Custody:

AMA Analytical Services, Inc.

Rodney Distance Client:

Address: 9826 Marrittsville Road

Randallstown, MD 21133

Attention: Rodney Distance

# CERTIFICATE OF ANALYSIS

Suspect Wiley Hodges Date Submitted:

Job Location: 6300 Brookville Road, Chevy Chase,

MD 20815

Report Date: 08/12/2019

Date Analyzed:

08/09/2019

08/12/2019

08/08/2019

Rodney Distance

Job Number: Not Provided Date Sampled: P.O. Number: Not Provided Person Submitting:

### Summary of Polarized Light Microscopy

Cilent Sample AMA Chrysotile Amosite Crocidolite Mineral Fiberglass Organic Synthetic Other Particulate Sample Sample Homogenetty Analyst Comments Sample Asbestos Wool Percent Color Percent Percent Percent Type Number

The following footnotes only apply to those samples which the total asbestos result is flagged with a note number.

1 TEM RECOMMENDATION - Please note, due to resolution limitations with optical microscopy and/or interference from matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos. It is recommended that the additional analytical technique of TEM be used to check for asbestos floers below the resolution limits of optical microscopy.

2 MATRIX REDUCTION RECOMMENDATION - Please note, due to interference from the matrix components of this sample, results which are reported via PLM as negative or trace (<1%) for asbestos may contain a significant quantity of asbestos which is obscured from view. It is recommended that the additional preparation technique of gravimetric reduction be performed on this sample to minimize the obscuring effects of matrix components, followed by reanalysis by PLM and/or TEM.

Analysis Method - EPA/600/R-93/116 dated July 1993

NAD = "No Asbestos Detected" TR = "Trace equals less than 1% of this component"

Uncertainty: For samples containing asbestos in range of 1-10% the CV is 0.43, 11-35% CV=0.55, >35 CV=0.23. All results are to be considered preliminary and subject to change unless signed by the Technical Director or Deputy.

Analyst(s): Peerawut Chaikeenee

Technical Director Michael Greenberg

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from us. Sample types, locations, and collection protocols are based upon the information provided by the persons submitting them and, unless collected by personnel of these Laboratories, we expressly disclaim any knowledge and liability for the accuracy and completeness of this information. Residual sample material will be discarded in accordance with the appropriate regulatory guidelines, unless otherwise requested by the client. NVLAP accreditation applies only to polarized light microscopy of bulk samples and transmission electron microscopy of AHERA air samples. This report must not be used to claim, and does not imply product certification, approval, or endorsement by NVLAP or any agency of the Federal Government. All rights reserved. AMA Analytical Services, Inc.

AMR Analytical Services, Inc. Focused on Results www amalab com AIHA-LAP (#100470) NVLAP (#101143-0) 4475 Fortus Blvd • Leoliam, MD 20706 (301) 459-2640 • (800) 346-0961 • Fax (301)		HAIN (	OF (	CUS	ТО	DY					er To	res)		5933 1813 -		
Mailing/Billing Information:  1. Client Name: Kordiney & Stance				nformati 16: _\$2	Second	· Wi	ley (	Hod	ح ب	f	A1					
2. Address 1: 9826 Practiotherile Road				ation: _6	500	Bre	OKZ	4/12	Ke	æde.	Libe PO	E.W.	Chase	HD 2	0815	
4 Address 3:				3. Job# P.O. # P.O. # 4. Contact Person: Rodorey Distance Cell: 410-814-9773 5. Collected by: Reciprog Lastoner Cell:												
5. Phone #:410-814-9273 For Reporting Info (Results provided as see	ix#:	5.	Collecter	d by:	wided	AMAN	ill agei	m defe	ulte c	£ 5.70 c	Cell	:	Il/fax to con	tacts on file.		
AFTER HOURS (must be pre-scheduled) AFTER Hours NORMA			BUSINESS HOURS    12   9 Pesults Required By Soon						REPORT FO:							
Ashestos Analysis  *PCM_Air.* Pleuse Indicate Filter Type:  O NIOSH 7400 (OTY)  Urberglass (QTY)  JEM_Air.* -Please Indicate Filter Type:  O ALERA (QTY)  NIOSH 7402 (QTY)  O Other (specify ) (QTY)  EMBOR HPA 600 - Visual Estimate (QTY)  O EPA Point Count (QTY)  O EPA Point Count (QTY)  O Grav. Reduction ELAF 198.6 (QTY)  O Other (specify ) (QTY)  Ashestos Soil PLAL (Qual) PLAL (Qual) FLATEM (Qual)  "It is necessed at the blank steples be submitted with advir and writer."	UNYSU GRESIDE J Vermic J Reside J Vermic J Quad. Quan.	198.4/Chatfield the PLM/TEM al Ash utilize pres/abs) Vacuum/Di s/area) Vacuum/Di s/area) Dust D6480 pres/abs). 198.2/EPA 100.2_ 00.1 uples received in gotter samples. a sheet are submitted.	(QTY)  Dust	(QTY) (QTY) (QTY) on unless of	(QTY	) I a noted.		to Paint ( Pb Dust Pb Air b Soil/Si b TCLP rinking /aste Wr b Furnace Analysis billection offection Spore-Ti Surface her (Spec	Water ater 11 Medi rap Swab Tape	Ct Pb_Pb_dis	LIQTY) LIQTY	OTY) O O O O O O O O O O O O O O O O O O O	l Cu(Q'Cu(Q'T	m Dust	"(QTY) (QTY)	
SAMPLE INFORMATION CLIENT ID # SAMPLE LOCATION II	DATE/	VOL (L) <sup>r</sup> Winc Anna	/anal	EVSIS	/3/	9/20	THE STATE OF	TATRI	12.00	1 34	1 3	N. AB		OMMENTS / L INSTRUCT	TONS	
3082017-6300- Kt Ingde day De				100			/	1				1				
3082019-6300-81 Inside August Dr. 32	1 Can 4:00 pm			1			Lorent							- 1-24111		
BB Exterior Windows 9	I at the second			l.			(great					M. W. N. JI.				
B4 Door Carl	Corg			~			500								н	
		<del> </del>					-		-			maca .			Total 6-0	
PCOL Edition Windows	5.41				1	-	-									
PCOZ of Builde	T		-				-			.00						
		1														
- And the second				- A Bar b Bar 40-												
						Ţ,										
Print Name		Signature				Date			Time							

305983 - PLM



August 19th, 2019

Suzanne Hodges 6300 Brookville Road Chevy Chase, MD, 20815

Dear Ms. Hodges,

Thank you for your request for a Rodent certification letter. This property is under maintenance for rodents with our company, at this time no additional inspections area required. The current abatement service will continue throughout the demolition and as long as you would like afterwards.

If you have any questions regarding this letter, contact our office at 301-891-2600. Sincerely,

# Alexandria Deters | Residential Sales Manager

**0:** 301-891-2600 | 703-810-1020

**D:** 240-485-2140Rodent

C: 301-455-8003

**E:** adeters@americanpest.net

W: www.americanpest.net

# Feather & Assoc

Tolbert V. Feather, Ph.D.

Advisors for: Landscape Development

Landscape Management, Plant Pest Management

Chevy Chase Village 5906 Connecticut Avenue Chevy Chase, MD 20815 August 7, 2019

### Tree Preservation Plan - 6300 Brookville Road

I recommend issuance of the Building Permit conditioned on the Owner's compliance with the tree preservation plan shown on the attached sheet and as stated below.

Attached is a map of the tree preservation plan for the residence 6300 Brookville Road Tree protection shall include:

- 1. Woodchips 12" deep shall be placed as shown on the plan. The woodchips may be removed only at the end of construction.
- 2. Super silt fencing shall not be used where woodchips are applied.
- 3. Post/grade beam foundation shall be used on the corner of the garage, as indicated on the plan.
- 4. Avoid injury to any live roots 2" or more in diameter when digging the post.
- 5. The Chevy Chase Village office shall be notified if there is any change in the construction plans that would impact the protected trees.

Woodchips 12" deep. No super silt fencing where woodchips are applied.

